


WIRE SPLICE AND SEAL INSTRUCTIONS - 2 CONDUCTOR PAIRS KIT 10585-2

WARNING: USE CONNECTORS ONLY FOR THEIR DESIGNATED PURPOSE. DO NOT USE FOR AC WIRING.

1




USE TO SEAL 2-WIRE
SENSOR AND/OR MP46x
PROBE CABLE SPLICES

SPLICE SEAL WIRE CONNECTOR PROVIDED BY PNEUMERCATOR


2

STRIP WIRES




* PROBE FIELD CABLE SHIELD WIRE HAS NO CONNECTION

2-WIRE SENSOR
OR MP46x PROBE
CABLE




3




TWIST WIRES

4



INSERT

5



**PULL ONE TWISTED LEAD PAIR
THROUGH EACH "V" AND BEND OVER**

6

SNAP ON OUTER SLEEVE

**DO NOT ROTATE OR
TWIST OUTER SLEEVE**

DO NOT REUSE

